

0119Z 31 DEC 62

TOP SECRET

Comm
AD-08A
Admin

DDR
DDP
C/SE
C/NE
Intell
RB

DIRECTOR

25X1A

TOP SECRET

[redacted]

OSA (1,2,3,4,5,6,7,8,9,10,11,12,13,14,15,

PRIORITY

S/C (16)

TOR: 0153Z 31 DEC 62

IN 60803

25X1A

25X1A

25X1A

PRIORITY

[redacted]

0360

[redacted]

25X1A

25X1A

REF [redacted] 0311

WE ARE VERY INTERESTED IN ANY EVALUATIONS THAT YOU MAY HAVE MADE IN REGARD TO CAUSE OF SYSTEM XII LIGHT TO ILLUMINATE ON MSN 3206 AS INDICATED IN REF MESSAGE. WE ARE HOPING THAT THE ANALYSIS OF [redacted] TAPES WILL PROVIDE TECHNICAL INFORMATION 25X1A WHICH WILL PROVIDE AN EXPLANATION FOR LIGHT ILLUMINATION. REQUEST A SUMMARY OF ANY INFORMATION THAT YOU MAY BE ABLE TO PROVIDE FROM THIS SOURCE OR FROM SYSTEM XII TECHNICIANS WHO MAY HAVE AN EXPERT OPINION AS TO THE TYPE AND SOURCE OF SIGNAL WHICH AFFECTED THIS EQUIPMENT ON THIS PARTICULAR MISSION.

END OF MESSAGE

TOP SECRET

TOP SECRET